

SB, Rebuild kit, KV9/12, 2021-04

SYMPTOM/DESCRIPTION

The newly introduced K1270 II does not fit the older KV9/12. For this reason the KV9/12 has been upgraded.

To use a new K1270II on an old KV9/12, you will need an upgrade kit.

To use an old K1270 on a new KV9/12, you will need a downgrade kit.

AFFECTED UNITS

K970

K1270

K1270 II

PARTS INFORMATION

Note: Old version of complete KV9/12 will be available until stock runs out.

Part Name	Old Part No	New Part No
KV9/12	587768402	599609801
Upgrade Kit, K1270II on old KV9/12	New part	529798401
Downgrade Kit, K1270 on new KV9/12	New Part	531109301

PROCEDURE

Due to the new 1270 II Fuel Tank, an update of the welded bracket that holds the machine is needed. Below is an instruction how to rebuild the KV using the upgrade kit.




Figure 1: Old and new bracket.



Figure 2: Nuts to disassemble.




Figure 3: Screw to disassemble.



Figure 4: Tap on the carrier.



Figure 5: Disassemble the nut holding the knob.



Figure 6: Pull the bracket outwards.




Figure 7: Parts to be moved and used with the new bracket.



Figure 8: Turning knob.




Figure 9: Position of turning knob.

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2021-04	SB-6564	Created